

RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIAT | DIRECT DIN REPREZENTANTA



Vehicle

BMW X6 xDrive40d, 225KW

WB 1



Development code E71
 Colour alpinweiss 3
 Actual integration level E070-15-11-500
 Start of warranty 07 April 2011



Technical Campaigns are available

▼ Technical campaigns

Status	Campaign number	Description	Reservation
Open	10026410100	Check or replace front propeller shaft Local campaign number: -	

▼ Special information

There are no Campaigns for this vehicle.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map could not be detected.

Installed map	Enabling code (subscri...	Latest navigation map included in subscription	Latest navigation map subject to charge
-	Enabling code valid for navigation maps with release date up to 31-Jul-2015 (SWID: 00280024).	Road Map Europe East PREMIUM 2016-1 Road Map Europe West PREMIUM 2016-1	Road Map Europe East PREMIUM (USB) 2021-1 Road Map Europe West PREMIUM (USB) 2021-1

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	X6 xDrive40d
Body	SC
Vehicle identification number (last 7 digits)	L4[]
Vehicle identification number (17 digits)	WB[] 1
Development code	E71
Steering	LL
Engine	N57S
Engine number	3[]9
Exhaust re-treatment	EURO5, A, PI/CI, M, N1 I
Transmission	AUT
Transmission number	008[]
Head unit serial number	No head unit could be found.
Drive	ALLR
Integration level, works	E[]03

Production date	28-Feb-2011
Production plant	SPARTANBURG
Delivery date	09-Apr-2011
Delivering retailer	AH <input type="text"/> E
National-market version	EUR
Paint code	300
Upholstery code	LUSW
Model code	FH01
Basic type	FH01
Lead type	FH01

Optional equipment

Optional equipment ex works:

01CB CO2 equipment
 0217 Active steering
 0230 Extra package, EU-speciifc
 0235 Towing hitch, detachable
 0316 automatic trunk lid mechanism
 0320 Deleted, model lettering
 0322 Comfort access
 0328 Footplate, aluminium
 0330 Sports package
 03AH Reversing camera and Top View
 0403 Glass roof, electrical
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0459 Seat adjustment, electric, with memory
 0464 Ski bag
 0481 Sports seat
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AD Interior trim strips, brushed aluminium
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0524 Adaptive Headlights

Retrofitted optional equipment:

This vehicle has no retrofits.

0534 Automatic air conditioning
0544 Cruise control with brake function
0548 Kilometre speedo
0563 Light package
0575 Additional 12V sockets
05AC High-beam assistant
05DA Passenger airbag deactivation
0609 Navigation system Professional
0610 Head-up display
0612 BMW Assist
0614 Internet preparation
0615 Extended BMW Online Information
0616 BMW Online
0620 Voice control
0633 Preparation, mobile phone, Business
0677 HiFi system Professional DSP
0698 Area-Code 2 for DVD
06AA BMW TeleServices
06AB Control, Teleservices
06FL USB/audio interface
06NF Music interface for Smartphone
06VC Control, Combox
0760 High gloss shadow line
0761 Individual sunshade glazing
0775 Headlining anthracite
07SP Navi Professional/m.-ph.prep. Bluetooth
0801 National version Germany
0851 Language version German
0863 Dealer List Europe
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08TH Road sign detection
08TL Dummy-SALAPA
08TN Daytime driv.lights adjus.via light menu
0925 Dummy-SALAPA
09WR Winter wheels
A090 90 Ah AGM battery
EWS4
KLE1

Control unit software version

Note: There is no information available about the software version of the control units.

Vehicle histories

	Date	Type	Vehicle mile...	Retailer Overview
—	08/12/2016	Key	171934 Km	01554 Key 1

11000
06/2018

0

11000
569

0

44000

0
12/2016

21000

19000
07/2019

0
06/2018

—	08/12/2016	Repair	171934 Km	01554	Job Job Job Job Job Job
---	------------	--------	-----------	-------	--

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Brake fluid service 5 FRU
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 2 184 843

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / engine 0 FRU
Flat rate unit I 11 99 000

MOTORÖL 5W-30 SYNTH Local 1.5
Part I FT97 77 7 777 0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / engine 0 FRU
Flat rate unit I 11 99 000

DIESEL KRAFT
Part I FT99 99 0 011 5

Local

20

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / lamps 0 FRU
Flat rate unit I 63 99 000

Replacing lamp bulb for front left side light 2 FRU
Flat rate unit I 63 99 645

Bulb 1
Part I 07 11 9 906 503

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash 3 FRU
Flat rate unit I 00 11 319

Fußraumreinigung (aussaugen) 1 FRU
Flat rate unit I 00 11 320

— Job

Description:

Considered as a repeat visit No

Customer's own words

Treuebonus Einbau Leuchtmittel 0 FRU
Flat rate unit I 00 02 007

— 02/08/2016 Repair 163100 Km 01554 Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing rear bumper panel Flat rate unit I 51 12 156	10 FRU
Painting upper section of rear bumper Flat rate unit I 99 69 047	32 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 603	2 FRU
Panel, bumper, primed, rear Part I 51 12 7 210 649	1
Mount, bumper, rear centre Part I 51 12 7 176 244	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Treuebonus 15% Rabatt Flat rate unit I 00 02 007	0 FRU
---	-------

— Job


Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash Flat rate unit I 00 11 319	3 FRU
Fußraumreinigung (aussaugen) Flat rate unit I 00 11 320	1 FRU

— 08/07/2016 Key 157941 Km 01554 Key 1



07/07/2016 Repair 157958 Km 01554 Job

Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Programming/encoding control unit(s) (with CAS) Flat rate unit I 61 00 720	5 FRU
Replacing gear selector lever Flat rate unit I 61 31 843	6 FRU
Gear selector switch Part I 61 31 9 228 610	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
Service, front brakes Flat rate unit I 00 00 612	7 FRU
Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 852 253	1
Clip Part I 34 11 6 798 126	2
Inner hex bolt Part I 34 21 1 161 806	2
Brake disc, ventilated Part I 34 11 6 868 938	2
Brake-pad paste Part I 83 19 2 158 851	2
Brake pad, wear sensor, front left	1

Brake pad wear sensor, front left
Part I 34 35 6 792 567

1

Sicherheitsreiniger 50ml
Part I VS99 99 0 000 7

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

DEKRA Abnahme Nachuntersuchung
Flat rate unit I 99 00 011

0 FRU

Inkasso HU laut beigefügter Rechnung
Part I VS9900011

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace charging pressure sensor
Flat rate unit I 13 62 535

3 FRU

Profile-gasket
Part I 11 61 7 807 480

6

Sensor, boost pressure
Part I 13 62 7 804 742

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash
Flat rate unit I 00 11 319

3 FRU


Fußraumreinigung (aussaugen)
Flat rate unit I 00 11 320

1 FRU

— 30/06/2016 Key

157038 Km

01554 Key 1



-2100 8.1 % 07/2017	-2100 396	-2100 396	-2100 396	14000	0 12/2016	34000	33000 07/2019	0 06/2016
---------------------------	--------------	--------------	--------------	-------	--------------	-------	------------------	--------------

—	30/06/2016	Repair	157071 Km	01554	Job Job Job Job Job Job Job
---	------------	--------	-----------	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash Flat rate unit I 00 11 319	3 FRU
Fetch and bring service zone Flat rate unit I 00 99 200	0 FRU
Kompakt-Check ohne Berechnung Flat rate unit I 00 99 500	3 FRU
Fußraumreinigung (aussaugen) Flat rate unit I 00 11 320	1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 7 808 443	1
Screw plug Part I 11 13 7 535 106	1
Windshield washer antifreeze Part I 83 12 2 296 207	12

MOTORÖL 5W-30 SYNTH
Part I FT97 77 7 777 0

Local

6.7

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Set, microfilter/carbon canister 1
Part I 64 11 9 248 294

Pollen-filter housing cleaner 1
Part I 83 19 2 180 509

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter 6 FRU
Flat rate unit I 00 00 604

Clamping bracket 1
Part I 13 32 7 789 220

Hose clamp 1
Part I 07 12 9 952 104

Fuel filter cartridge 1
Part I 13 32 7 811 227

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element 1 FRU
Flat rate unit I 00 00 602

Air filter element 1
Part I 13 71 7 811 026

— Job

Description:

Considered as a repeat visit No

Customer's own words

DEKRA Abnahme Flat rate unit I 99 00 011		0 FRU
Abgasuntersuchung Flat rate unit I 00 00 441		6 FRU
Inkasso HU laut beigefügter Rechnung Part I VS9900011	Local	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006		5 FRU

— Job










Description:

Considered as a repeat visit No

Customer's own words

Pflegepaket Basis Flat rate unit I 00 11 999		18 FRU
---	--	--------

— 16/11/2015 Key 139277 Km 29843 Key 1

 16000 07/2017	 16000 623	 16000 623	 16000 623	 29000	 0 12/2016	 60000	 60000 07/2019	 0 06/2016
---	---	---	---	--	--	--	---	---

— 16/11/2015 Repair 139292 Km 29843 Job
Job
Job

Description: Leistungsverlust, prüfen, KVA erstellen

Considered as a repeat visit No

Customer's own words

Clean cylinder head intake channels and intake plenums	62 FRU
Flat rate unit I 11 12 800	

Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	

Removing and installing intake manifold	13 FRU
Flat rate unit I 11 61 550	

Replacing all glow plugs	8 FRU
Flat rate unit I 12 23 505	

Service consultation with customer at vehicle without service ticket	0 FRU
Flat rate unit I 00 52 053	

Performing vehicle test	4 FRU
Flat rate unit I 00 00 006	

Vehicle diagnosis - carrying out the ABL	6 FRU
Flat rate unit I 61 00 006	

Job time without allowance for / engine	26 FRU
Flat rate unit I 11 99 000	

Bilddokumentation erstellen	2 FRU
Flat rate unit I -	

T-Connector	1
Part I 11 72 1 439 973	

ASA-Bolt	10
Part I 07 12 9 905 905	

Intake manifold with flap control	1
Part I 11 61 8 511 363	

O-ring	1
Part I 11 61 8 511 416	

Vacuum hose black	1
Part I 11 74 7 797 129	

Torx bolt	1
Part I 11 31 1 715 412	

— Job

Description: Fahrzeugpflege

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fußraum saugen
Flat rate unit I -

4 FRU

— Job

Description: SEW

Considered as a repeat visit No







Customer's own words

— 07/07/2015 Key

129969 Km

29843

Key 1



— 07/07/2015 Repair

129969 Km

29843

Job

Job

Job

Job

Job

Job

Job

— Job

Description: Wartung

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

0 FRU

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Additional job, service - recirculating air filter

3 FRU

Flat rate unit | 00 00 617

Microfilter service	2 FRU
Flat rate unit 00 00 616	

Lichttest durchführen	2 FRU
Flat rate unit -	

Set oil-filter element	1
Part 11 42 7 808 443	

Pollen-filter housing cleaner	1
Part 83 19 2 180 509	

Set, microfilter/carbon canister	1
Part 64 11 9 248 294	

Air filter element	1
Part 13 71 7 811 026	

Microfilter, recirculated air	1
Part 64 31 9 194 098	

Castrol Edge Prof. 0W30	Local	6.7
Part FTT0030		

— Job

Description: Fzg.-Check

Considered as a repeat visit No

Customer's own words

Service, vehicle check	8 FRU
Flat rate unit 00 00 624	

Button top	1
Part 72 11 1 950 829	

Button bottom	1
Part 72 11 1 917 406	

— Job

Description: Bremse hinten

Considered as a repeat visit No

Customer's own words

Service, rear brakes	12 FRU
Flat rate unit 00 00 614	

Checking brake pad thickness	1 FRU
------------------------------	-------

Flat rate unit | 34 00 510

Perform brake test on test stand Flat rate unit 34 00 509	6 FRU
--	-------

Removing and installing or replacing all parking brake shoes Flat rate unit 34 41 660	5 FRU
--	-------

Removing and installing or replacing both rear brake discs Flat rate unit 34 21 932	4 FRU
--	-------

Repair kit, brake pads asbestos-free Part 34 21 6 776 937	1
--	---

Brake cleaner Part 83 19 2 153 367	1
---	---

Brake pad wear sensor Part 34 35 6 854 168	1
---	---

Brake-pad paste Part 83 19 2 158 851	2
---	---

Clip Part 34 21 6 758 059	2
--------------------------------	---

Repair kit springs Part 34 41 0 038 346	1
--	---

Repair kit brake shoe Part 34 41 6 780 041	1
---	---

Expanding lock Part 34 41 6 851 439	2
--	---

Adjusting screw Part 34 41 6 851 437	2
---	---

Brake disc, ventilated Part 34 21 6 868 940	2
--	---

— Job

Description: Scheinfehler Aktivlenkung, konnte gelöscht werden

Considered as a repeat visit No

Customer's own words

Vehicle diagnosis - carrying out the ABL Flat rate unit 61 00 006	5 FRU
--	-------

Performing vehicle test	2 FRU
-------------------------	-------

Flat rate unit I 00 00 556

— Job

Description: Wäsche (Innen/Aussen)

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fußraum saugen 4 FRU
Flat rate unit I -

— Job

Description: Navi-Update 2015 aufspielen

Considered as a repeat visit No

Customer's own words

Navigation updaten 1 FRU
Flat rate unit I -

USB update navigation map Europe Premium 1
Part I 65 90 2 350 679

En. code CIC map Europe Premium update 1
Part I 65 90 2 350 592

— Job

Description: Blende Stoßfänger für AHK fehlt, bitte neue


Considered as a repeat visit No

Customer's own words

Blende AHK montieren 2 FRU
Flat rate unit I -

Trailer coupling flap 1
Part I 51 12 7 192 733

— 15/12/2014 Key 114273 Km 29843 Key 1



— 15/12/2014 Repair 114283 Km 29843 Job Job

— Job

Description: Service**Considered as a repeat visit** No**Customer's own words**

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
---	-------

Service, advisory consultation at vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

Service, front brakes Flat rate unit I 00 00 612	7 FRU
---	-------

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Brake-pad paste Part I 83 19 2 158 851	2
---	---

Clip Part I 34 11 6 798 126	2
--------------------------------	---

Brake disc, ventilated Part I 34 11 6 868 938	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Repair kit, brake pads asbestos-free Part I 34 11 6 852 253	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 792 567	1
---	---

Brake cleaner Part I 83 19 2 153 367	1
---	---

— Job

Description: Service**Considered as a repeat visit** No**Customer's own words**

Brake fluid service Flat rate unit I 00 00 618	5 FRU
---	-------

Brake fluid DOT4 LV, low viscosity
Part I 83 13 0 443 026

1

— Job

Description: Fahrzeugpflege

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fussmatten saugen
Flat rate unit I -

4 FRU

— Job

Description: SEW

Considered as a repeat visit No









Customer's own words

— 25/06/2014 Key

98567 Km

29843

Key 1



— 25/06/2014 Repair

98580 Km

29843

Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description: Ölservice fällig

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit I 00 00 616

2 FRU

Service - air filter element
Flat rate unit I 00 00 602

1 FRU

Service fuel filter

6 FRU

Service fuer filter Flat rate unit I 00 00 604		0 FRU
Engine oil service Flat rate unit I 00 00 610		3 FRU
Service - standard scope Flat rate unit I 00 00 105		2 FRU
Service, advisory consultation at vehicle Flat rate unit I 00 52 050		0 FRU
Lichttest durchführen Flat rate unit I -		2 FRU
Pollen-filter housing cleaner Part I 83 19 2 180 509		1
Windshield washer antifreeze Part I 83 12 2 298 207		0.2
Hose clamp Part I 16 12 1 180 240		1
Set, microfilter/carbon canister Part I 64 11 9 248 294		1
Air filter element Part I 13 71 7 811 026		1
Fuel filter cartridge Part I 13 32 7 811 227		1
Set oil-filter element Part I 11 42 7 808 443		1
Castrol Edge Prof. 0W30 Part I FTT0030	Local	6.7

— Job

Description: HU/AU fällig

Considered as a repeat visit No

Customer's own words

Exhaust emission inspection Flat rate unit I 00 00 440		8 FRU
---	--	-------

— Job

Description: Navi Update aufspielen

Considered as a repeat visit No

Customer's own words

Naviupdate aufspielen Flat rate unit I -	3 FRU
Update DVD Road Map Europe Premium Part I 65 90 2 350 593	1
En. code CIC map Europe Premium update Part I 65 90 2 350 592	1

— Job

Description: Geräusch vo.re. Radlauf eim einlenken,prüfen

Considered as a repeat visit No

Customer's own words

Localizing body problem(s) Flat rate unit I 51 00 001	3 FRU
Removing and installing/replacing front and rear underbody protection Flat rate unit I 51 47 995	3 FRU

— Job

Description: Fzg. ruckelt beim anfahren im kalten Zustand,prüfe

Considered as a repeat visit No

Customer's own words

Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	7 FRU
Removing and installing or replacing filtered air pipe Flat rate unit I 13 71 535	8 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Pipe Part I 13 71 7 810 772	1
O-ring Part I 11 12 7 823 944	1

— Job

Description: Motorwäsche durchführen

Considered as a repeat visit No

Customer's own words

Cleaning engine and engine compartment
Flat rate unit I 00 11 359

2 FRU

— Job

Description: Fahrzeugpflege

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fussmatten saugen
Flat rate unit I -

4 FRU

— Job

Description: SEW

Considered as a repeat visit No









Customer's own words

— 28/11/2013 Key

78049 Km

29843

Key 1



— 28/11/2013 Repair

78049 Km

29843

Job

Job

Job

Job

Job

Job

— Job

Description: Batterientladung wird angezeigt

Considered as a repeat visit No

Customer's own words

Checking vehicle battery with battery tester
Flat rate unit I 61 20 505

2 FRU

Carrying out vehicle battery energy diagnosis
Flat rate unit I 61 20 502

1 FRU

Check vehicle battery
Flat rate unit I 61 20 515

2 FRU

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Replacing vehicle battery – registering battery replacement Flat rate unit I 61 21 517	6 FRU
Support voltage of the vehicle electrical system / recharge vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Original BMW AGM-battery Part I 61 21 6 924 023	1

— Job

Description: Schlüsselbatterie ers.

Considered as a repeat visit No

Customer's own words

Handsenderbatterie ers. Flat rate unit I -	1 FRU
Battery Part I 66 12 6 912 985	1

— Job

Description: Wartung

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
Service - standard scope Flat rate unit I 00 00 105	2 FRU
Microfilter service Flat rate unit I 00 00 616	2 FRU
Set oil-filter element Part I 11 42 7 808 443	1
Set, microfilter/carbon canister Part I 64 11 9 248 294	1
Pollen-filter housing cleaner Part I 83 19 2 180 509	1
Windshield washer antifreeze	1

Castrol Edge Prof. 0W30
Part I FTT0030

Local

6.7

— Job

Description: Ausen/Innenreinigung

Considered as a repeat visit No

Customer's own words

Wagenoberwäsche und Innen-
reinigung
Flat rate unit I -

12 FRU

— Job

Description: SEW

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Dichtungspflege
Flat rate unit I -








1 FRU

— 12/07/2013 Key

67284 Km

29843

Key 1



— 12/07/2013 Repair

67294 Km

29843

Job
Job
Job
Job
Job

— Job

Description: Service

Considered as a repeat visit No

Customer's own words

Adjusting parking brake Flat rate unit I 34 41 506	3 FRU
Service - standard scope Flat rate unit I 00 00 105	2 FRU
Service, rear brakes Flat rate unit I 00 00 614	12 FRU
Service, advisory consultation at vehicle Flat rate unit I 00 52 050	0 FRU
Lichttest durchführen Flat rate unit I -	2 FRU
Clip Part I 34 21 6 758 059	2
Inner hex bolt Part I 34 21 1 161 806	2
Brake pad wear sensor Part I 34 35 6 854 168	1
Repair kit, brake pads asbestos-free Part I 34 21 6 776 937	1
Brake-pad paste Part I 83 19 2 158 851	2
Brake cleaner Part I 83 19 2 153 367	1
Expanding rivet Part I 51 46 7 002 606	6

— Job

Description: Service

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	8 FRU
Blind plug Part I 51 71 8 170 298	4
Windshield washer antifreeze Part I 83 12 2 298 206	1

— Job

Description: Reifen auf Fremdkörper prüfen, KVA erstellen

Considered as a repeat visit No

Customer's own words

Initialising tyre failure indicator 1 FRU
Flat rate unit I 36 11 500

Reifencheck Winterreifen vr defekt 1 FRU
Flat rate unit I -

— Job

Description: prüfen, KVA erstellen, Kulanz stellen

Considered as a repeat visit No

Customer's own words

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556

Vehicle diagnosis - carrying out the ABL 4 FRU
Flat rate unit I 61 00 006

— Job







Description: Fahrzeugpflege

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fussmatten saugen 4 FRU
Flat rate unit I -

— 01/03/2013 Key 54863 Km 29843 Key 1



— 01/03/2013 Repair 54871 Km 29843 Job Job

— Job

Description: Bremsenservice vorne fällig Bremsen hinten prüfen

Considered as a repeat visit No

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Service - standard scope Flat rate unit I 00 00 105	2 FRU
Service, front brakes Flat rate unit I 00 00 612	7 FRU
Inner hex bolt Part I 34 21 1 161 806	2
Brake disc, ventilated Part I 34 11 6 793 244	2
Brake-pad paste Part I 83 19 2 158 851	2
Brake cleaner Part I 83 19 2 153 367	1
Brake pad wear sensor, front left Part I 34 35 6 792 567	1
Repair kit, brake pads asbestos-free Part I 34 11 6 852 253	1

— Job


Description: Fahrzeugpflege

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fussmatten saugen Flat rate unit I -	4 FRU
---	-------

— 29/01/2013 Key 51942 Km 29843 Key 1



— 29/01/2013 Repair 51942 Km 29843 Job
Job
Job

— Job

Description: Ölservice durchführen

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
Service - air filter element Flat rate unit I 00 00 602	1 FRU
Service fuel filter Flat rate unit I 00 00 604	7 FRU
Engine oil service Flat rate unit I 00 00 610	3 FRU
Service - standard scope Flat rate unit I 00 00 105	2 FRU
Windshield washer antifreeze Part I 83 12 2 298 206	1
Pollen-filter housing cleaner Part I 83 19 2 180 509	1
Hose clamp Part I 16 12 1 180 240	1
Fuel filter cartridge Part I 13 32 7 811 227	1
Set, microfilter/carbon canister Part I 64 11 9 248 294	1
Set oil-filter element Part I 11 42 7 808 443	1
Air filter element Part I 13 71 7 811 026	1
CASTROL EDGE PROF. 0W30 Part I FTT0030	Local 6.7

— Job

Description: Bremsflüssigkeit wechseln

Considered as a repeat visit No

Customer's own words

Part I 13 32 7 811 227	1
------------------------	---

Brake fluid service 6 FRU
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 2 184 843

— Job

Description: Fahrzeugpflege

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fussmatten saugen 4 FRU
Flat rate unit I -

— 03/07/2012 Repair 38592 Km 29843 Job
Job

— Job

Description: Frontscheibe ersetzen

Considered as a repeat visit No

Customer's own words

Additional work with rain-light-solar-condensation 5 FRU
sensor
Flat rate unit I 61 35 998

Replacing windshield 34 FRU
Flat rate unit I 51 31 011

Cover, windshield, top 1
Part I 51 31 7 179 738

Clip 10
Part I 51 31 7 064 098

Windscreen, green, rain sensor / HUD 1
Part I 51 31 7 188 781

Spacer, adhesive 10
Part I 51 31 7 186 167

Repair kit, window glass, cold, 1 hour 1
Part I 83 19 0 444 141

Clip 10
Part I 51 13 7 192 768

Clip 10

Part I 51 31 7 177 029

Window-glass adhesive, cold, 1 hour Part I 83 19 0 444 144	1
---	---

Rain/light/solar and fogging sensor Part I 61 35 9 254 025	1
---	---

!!! unknown BMW-Id 99180000000 Feinstaubplakette !!! Part I 99 18 0 000 000	Local	1
---	-------	---

— Job

Description: Reinigung / Wäsche

Considered as a repeat visit No

Customer's own words

Fzg. Oberwäsche und Fussmatten saugen Flat rate unit I -	4 FRU
---	-------

—	05/04/2012	Repair	24859 Km	29843	Job Job
---	------------	--------	----------	-------	------------

— Job

Description: Service

Considered as a repeat visit No

Customer's own words

Service, advisory consultation at vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

(Statutory) vehicle inspection Flat rate unit I 00 12 159	1 FRU
--	-------

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 7 808 443	1
--	---

Oil filter cover Part I 11 42 7 808 440	1
--	---

CASTROL EDGE PROF. 0W30 Part I FTT0030	Local	6.7
---	-------	-----

Scheibenklar
Part I FT83 12 2 181 2

Local

1

— Job

Description: Service

Considered as a repeat visit No

Customer's own words

Additional job, service - recirculating air filter Flat rate unit I 00 00 617	3 FRU
--	-------

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter, recirculated air Part I 64 31 9 194 098	1
---	---

Set, microfilter/carbon canister Part I 64 11 9 248 294	1
--	---

— 01/02/2012 Repair 19500 Km 29843 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Gutachter für Schadenfeststellung nach Entwendung
ist bestellt.
div Steuergerät zur Ringbruchdiagnose freigelegt.

Removing and installing/replacing the complete lock barrel on the left or right front door Flat rate unit I 51 21 640	2 FRU
---	-------

Replacing control unit for car access system Flat rate unit I 61 35 516	6 FRU
--	-------

Job time without allowance for / body equipment Flat rate unit I 51 99 000	12 FRU
---	--------

Removing and installing/replacing the outside door handle at the front left or right Flat rate unit I 51 21 770	4 FRU
---	-------

Replacing rear bumper panel Flat rate unit I 51 12 592	8 FRU
---	-------

Service, advisory consultation at vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

Replacing footwell module Flat rate unit I 61 35 616	10 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 604	4 FRU
Initialising/normalising slide/tilt sunroof, power window regulator and steering column adjustment Flat rate unit I 61 00 983	1 FRU
Adjusting steering angle sensor Flat rate unit I 61 31 996	1 FRU
Performing vehicle test Flat rate unit I 00 00 006	4 FRU
Initialising tyre failure indicator Flat rate unit I 36 11 500	1 FRU
Continuing vehicle test and performing Quick delete Flat rate unit I 61 00 980	2 FRU
Programming/encoding control unit(s) (with CAS) Flat rate unit I 61 00 720	5 FRU
Rechecking telematics control unit Flat rate unit I 84 11 905	2 FRU
Carrying out vehicle battery "power reset" Flat rate unit I 61 20 908	2 FRU
Removing and installing/ replacing START-STOP button Flat rate unit I 61 31 514	2 FRU
Removing and installing or replacing centre console switch centre Flat rate unit I 61 31 552	5 FRU
Removing and installing the FZD Flat rate unit I 61 31 543	2 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	15 FRU
Support voltage of the vehicle electrical system / recharge vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Job time without allowance for / communication systems Flat rate unit I 84 99 000	4 FRU
Removing and installing telematics control unit	5 FRU

Flat rate unit | 84 11 660

Removing and installing/replacing the outside door handle support including lock barrel, left or right
Flat rate unit | 51 21 625

Replacing left or right front door trim panel
Flat rate unit | 51 41 504

(Statutory) vehicle inspection
Flat rate unit | 00 12 159

Job time without allowance for / body equipment
Flat rate unit | 51 99 000

Removing and installing/replacing the sound insulation at the front left or right door
Flat rate unit | 51 48 560

Removing and installing left or right front door trim panel
Flat rate unit | 51 41 503

Fahrzeug-Verbringung
Flat rate unit | 14 00 014

Panel, bumper, primed, rear
Part | 51 12 7 210 649

Mount, bumper rear right
Part | 51 12 7 176 246

grab handle, paint finish, left
Part | 51 21 7 207 565

Rear fog light/reflector, right
Part | 63 14 7 187 220

Rear light in the side panel, right
Part | 63 21 7 179 984

Sound insulating door front left
Part | 51 48 7 202 065

Trims, bumper, rear
Part | 51 12 2 154 633

Seal, rear light, side panel right
Part | 63 21 7 153 720

Lock with code left
Part | 51 21 7 212 873

cover, lock cylinder primed, left

Part I 51 21 7 162 439		
Base, lock cylinder, left Part I 51 21 7 060 667		1
Handle bracket base, left Part I 51 21 7 060 293		1
Sound insulating door rear left Part I 51 48 7 202 067		1
Sound insulating door front right Part I 51 48 7 202 066		1
Butyl tape Terostat 81 Part I 83 19 0 153 321		1
Sound insulating door rear right Part I 51 48 7 202 068		1
Set uniform lock.syst. w/CAS cntrl(code) Part I 51 21 0 036 806		1
Expanding rivet, black Part I 51 77 7 171 004		15
Sound insulating door front left Part I 51 48 7 202 065		1
Switch, deactivation,fr.passenger airbag Part I 61 31 9 196 886		1
Loudspeaker cover Part I 51 41 6 969 392		1
Door trim panel, leather, front left Part I 51 41 7 244 895		1
Expanding rivet, black Part I 51 77 7 171 004		10
Retainer, speaker cover Part I 07 14 7 243 883		10
Radhaus vorne rechts lackieren 20 AW Part I FT0000154	Local	1
Stoßstange hinten lackier en 43 AW Part I FT0000154	Local	1
Neu erstellt Fahrgestelln r. lackieren 6 AW Part I FT0000154	Local	1
Blenden lackieren 9 AW Part I FT0000154	Local	1

— 01/02/2012 Repair

19500 Km

29843 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Gutachter für Schadenfeststellung nach Entwendung ist bestellt.
div Steuergerät zur Ringbruchdiagnose freigelegt.
neue Rechnung wird erstellt, einige Teile fehlten noch!

Replacing rear bumper panel Flat rate unit I 51 12 592	-8 FRU
Service, advisory consultation at vehicle Flat rate unit I 00 52 050	0 FRU
Job time without allowance for / body equipment Flat rate unit I 51 99 000	-12 FRU
Removing and installing/replacing the outside door handle at the front left or right Flat rate unit I 51 21 770	-4 FRU
Continuing vehicle test and performing Quick delete Flat rate unit I 61 00 980	-2 FRU
Programming/encoding control unit(s) (with CAS) Flat rate unit I 61 00 720	-5 FRU
Replacing footwell module Flat rate unit I 61 35 616	-10 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 604	-4 FRU
Removing and installing/replacing the complete lock barrel on the left or right front door Flat rate unit I 51 21 640	-2 FRU
Replacing control unit for car access system Flat rate unit I 61 35 516	-6 FRU
Performing vehicle test Flat rate unit I 00 00 006	-4 FRU
Initialising tyre failure indicator Flat rate unit I 36 11 500	-1 FRU
Vehicle diagnosis - carrying out the ABL	-15 FRU

Flat rate unit | 61 00 006

Support voltage of the vehicle electrical system /
recharge vehicle electrical system battery -1 FRU
Flat rate unit | 61 21 528

Rechecking telematics control unit -2 FRU
Flat rate unit | 84 11 905

Carrying out vehicle battery "power reset" -2 FRU
Flat rate unit | 61 20 908

Initialising/normalising slide/tilt sunroof, power window
regulator and steering column adjustment -1 FRU
Flat rate unit | 61 00 983

Adjusting steering angle sensor -1 FRU
Flat rate unit | 61 31 996

Removing and installing the FZD -2 FRU
Flat rate unit | 61 31 543

(Statutory) vehicle inspection 0 FRU
Flat rate unit | 00 12 159

Job time without allowance for / body equipment -6 FRU
Flat rate unit | 51 99 000

Job time without allowance for / communication
systems -4 FRU
Flat rate unit | 84 99 000

Removing and installing telematics control unit -5 FRU
Flat rate unit | 84 11 660

Removing and installing/ replacing START-STOP
button -2 FRU
Flat rate unit | 61 31 514

Removing and installing or replacing centre console
switch centre -5 FRU
Flat rate unit | 61 31 552

Fahrzeug-Verbringung -12 FRU
Flat rate unit | 14 00 014

Sound insulating door rear right -1
Part | 51 48 7 202 068

Sound insulating door rear left -1
Part | 51 48 7 202 067

Butyl tape Terostat 81 -1
Part | 83 19 0 153 321

Mount, bumper rear right Part I 51 12 7 176 246	-1
Handle bracket base, left Part I 51 21 7 060 293	-1
Lock with code left Part I 51 21 7 212 873	-1
Sound insulating door front left Part I 51 48 7 202 065	-1
Base, lock cylinder, left Part I 51 21 7 060 667	-1
Rear fog light/reflector, right Part I 63 14 7 187 220	-1
Panel, bumper, primed, rear Part I 51 12 7 210 649	-1
cover, lock cylinder primed, left Part I 51 21 7 162 439	-1
grab handle, paint finish, left Part I 51 21 7 207 565	-1
Switch, deactivation,fr.passenger airbag Part I 61 31 9 196 886	-1
Set uniform lock.syst. w/CAS cntrl(code) Part I 51 21 0 036 806	-1
Sound insulating door front right Part I 51 48 7 202 066	-1
Sound insulating door front left Part I 51 48 7 202 065	-1
Seal, rear light, side panel right Part I 63 21 7 153 720	-1
Rear light in the side panel, right Part I 63 21 7 179 984	-1
Expanding rivet, black Part I 51 77 7 171 004	-15
Trims, bumper, rear Part I 51 12 2 154 633	-1
Stoßstange hinten lackier en 43 AW Part I FT0000154	Local 1

31/01/2012 Repair

19500 Km

29843

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words zu Unfallschaden, Fzg. war nicht fertig

Ersatzfahrzeug BMW 5er

2 FRU

Flat rate unit I -

20/01/2012 Repair

19500 Km

29843

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Gutachter für Schadenfeststellung nach Entwendung ist bestellt.
div Steuergerät zur Ringbruchdiagnose freigelegt.

Replacing control unit for car access system

6 FRU

Flat rate unit I 61 35 516

Replacing footwell module

10 FRU

Flat rate unit I 61 35 616

Removing and installing/replacing the outside door handle at the front left or right

4 FRU

Flat rate unit I 51 21 770

Removing and installing/replacing the complete lock barrel on the left or right front door

2 FRU

Flat rate unit I 51 21 640

Programming/encoding control unit(s) (with CAS)

5 FRU

Flat rate unit I 61 00 720

Job time without allowance for / body equipment

12 FRU

Flat rate unit I 51 99 000

Carrying out vehicle battery "power reset"

2 FRU

Flat rate unit I 61 20 908

Continuing vehicle test and performing Quick delete

2 FRU

Flat rate unit I 61 00 980

Service, advisory consultation at vehicle

0 FRU

Flat rate unit I 00 52 050

Additional work with Park Distance Control

4 FRU I

Additional work with Park Distance Control Flat rate unit I 66 20 604	4 FRU
Replacing rear bumper panel Flat rate unit I 51 12 592	8 FRU
Removing and installing or replacing centre console switch centre Flat rate unit I 61 31 552	5 FRU
Job time without allowance for / communication systems Flat rate unit I 84 99 000	4 FRU
Removing and installing the FZD Flat rate unit I 61 31 543	2 FRU
Removing and installing/ replacing START-STOP button Flat rate unit I 61 31 514	2 FRU
Job time without allowance for / body equipment Flat rate unit I 51 99 000	6 FRU
(Statutory) vehicle inspection Flat rate unit I 00 12 159	0 FRU
Adjusting steering angle sensor Flat rate unit I 61 31 996	1 FRU
Rechecking telematics control unit Flat rate unit I 84 11 905	2 FRU
Initialising tyre failure indicator Flat rate unit I 36 11 500	1 FRU
Initialising/normalising slide/tilt sunroof, power window regulator and steering column adjustment Flat rate unit I 61 00 983	1 FRU
Support voltage of the vehicle electrical system / recharge vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Performing vehicle test Flat rate unit I 00 00 006	4 FRU
Removing and installing telematics control unit Flat rate unit I 84 11 660	5 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	15 FRU
Fahrzeug-Verbringung Flat rate unit I 14 00 014	12 FRU

grab handle, paint finish, left Part I 51 21 7 207 565	1
Rear fog light/reflector, right Part I 63 14 7 187 220	1
Lock with code left Part I 51 21 7 212 873	1
cover, lock cylinder primed, left Part I 51 21 7 162 439	1
Base, lock cylinder, left Part I 51 21 7 060 667	1
Handle bracket base, left Part I 51 21 7 060 293	1
Rear light in the side panel, right Part I 63 21 7 179 984	1
Sound insulating door front left Part I 51 48 7 202 065	1
Panel, bumper, primed, rear Part I 51 12 7 210 649	1
Mount, bumper rear right Part I 51 12 7 176 246	1
Butyl tape Terostat 81 Part I 83 19 0 153 321	1
Sound insulating door rear right Part I 51 48 7 202 068	1
Trims, bumper, rear Part I 51 12 2 154 633	1
Seal, rear light, side panel right Part I 63 21 7 153 720	1
Set uniform lock.syst. w/CAS cntrl(code) Part I 51 21 0 036 806	1
Expanding rivet, black Part I 51 77 7 171 004	15
Sound insulating door front left Part I 51 48 7 202 065	1
Switch, deactivation,fr.passenger airbag Part I 61 31 9 196 886	1
Sound insulating door rear left	1

Sound insulating door rear left
Part I 51 48 7 202 067

Sound insulating door front right
Part I 51 48 7 202 066

Stoßstange hinten lackier en 43 AW
Part I FT0000154

Local

1

— 08/08/2011 Repair 10694 Km 03786 Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Working time without specification/exhaust system
Flat rate unit I 18 99 000

18 FRU

Relieving the tension/aligning the exhaust system
Flat rate unit I 18 00 008

6 FRU

Set, tailpipe trims, chrome
Part I 18 30 2 185 389

1

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Job time without allowance for / body equipment
Flat rate unit I 51 99 000

3 FRU

Removing and installing rear bumper panel
Flat rate unit I 51 12 156

10 FRU

Additional work with Park Distance Control
Flat rate unit I 66 20 603

2 FRU

Rear fog light/reflector, right
Part I 63 14 7 187 220

1

Expanding rivet
Part I 51 71 7 002 953

10

— Job

Description:

Considered as a repeat visit No

Customer's own words none

(Statutory) vehicle inspection
Flat rate unit I 00 12 159

5 FRU

— 10/06/2011 Repair 10 Km 02766 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words none

Rechnung Kravag Logistic vom 18.05.11, Versicheru Local
Part I FT0000154

1



RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIAT | DIRECT DIN REPREZENTANTA

