

RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIAT | DIRECT DIN REPREZENTANTA



Cover - Digital Service Report (History)

This report contains the following acknowledgements



Overview 7	04.02.2016
Overview 6	16.03.2015
Overview 5	25.06.2014
Overview 4	22.10.2013
Overview 3	24.04.2013
Overview 2	26.09.2012
Overview 1	08.03.2012

Service history has been printed by



Mercedes-Benz

Service station signature/stamp



Digital Service Report (History)

Vehicle data	
Vehicle	E 250 CDI 4MATIC
First registration	20.06.2011
FIN	WD [redacted] 202

Next 02.2017 **Next test technical** 06.2016

Service 157130 km
 (For the next review please note the additional information about the vehicle (service book and Assist system indications))

Current Service Report

Mercedes-Benz Mercedes-Benz [redacted] s.zawa Sp. with Date 04.02.2016
 o.o. [redacted]
 ul. G [redacted] Repair Order No. 16 [redacted] 1
 Wars [redacted] Run 137130 km

Serviced Service

Service A
 Workshop code GD0V
 Time Remaining 40 Days
 Remaining mileage -1700 km

Additional work

- Filter Replacement (cabin)
- Air filter cartridge replacement
- Automatic transmission: oil and filter exchange
- Service A
- Engine: filter and oil replacement motor
- Brake fluid replacement

Oil quality/viscosity

Description Engine oil
 Viscosity 5W-30
 ' 229.51
 Description Automatic transmission
 Viscosity
 ' 236.15

For next review

- Mercedes-Benz
- No corrosion guarantee perforation

Interval compatible with guidelines of Mercedes-Benz AG

- Complies with

Additional activities performed in accordance with the Mercedes-Benz AG guidelines

- Completed



Mercedes-Benz

Service Report 5

Mercedes-Benz	Merc	zawa Sp.	Date	25.06.2014
	z o.o.		Repair Order No.	51 3
	ul. G		Run	95245 km
	Wars			

Serviced

Service	A
Workshop code	505
Time Remaining	120 Days
Remaining mileage	1800 km
Oil quality/viscosity	
Description	Engine oil
Viscosity	5W-30

Additional work

Filter Replacement (cabin)	<input checked="" type="checkbox"/>
Air filter cartridge replacement	<input checked="" type="checkbox"/>
Engine: replacement of filter and engine oil	<input checked="" type="checkbox"/>

For next review

Mercedes-Benz No corrosion guarantee perforation	<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>

Interval compatible with guidelines of Mercedes-Benz AG

Complies with

Additional activities performed in accordance with the Mercedes-Benz AG guidelines

Completed

Service Report 4

Mercedes-Benz	Merc	szawa Sp. with	Date	22.10.2013
	o.o.		Repair Order No.	41 80
	ul. G		Run	77028 km
	Wars			

Serviced

Service	Service B
Workshop code	5E0K
Time Remaining	185 Days
Remaining mileage	2000 km
Oil quality/viscosity	
Description	Engine oil
Viscosity	5W-30
	229.51

Additional work

Air filter cartridge replacement	<input checked="" type="checkbox"/>
Fuel filter replacement	<input checked="" type="checkbox"/>
Engine: filter and oil replacement motor	<input checked="" type="checkbox"/>
Brake fluid replacement	<input checked="" type="checkbox"/>

For next review

Mercedes-Benz No corrosion guarantee perforation	<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>

Interval compatible with guidelines of Mercedes-Benz AG

Complies with

Additional activities performed in accordance with the Mercedes-Benz AG guidelines

Completed



Service Report 3

Mercedes-Benz Zbigniew [redacted] wakovsky Date 24.04.2013
 ul. Eu [redacted] Repair Order No. 35 [redacted]
 Wars [redacted] Run 58979 km

Serviced

Service Service A
 Workshop code 850D
 Time Remaining 155 Days
 Remaining mileage 100 km

Oil quality/viscosity

Description Engine oil
 Viscosity MB
 ' 229.51

Additional work

Brake lining replacement front axle
 Brake lining replacement rear axle
 Air filter cartridge replacement
 Engine: filter and oil replacement motor

For next review

Mercedes-Benz
 No corrosion guarantee perforation

Interval compatible with guidelines of Mercedes-Benz AG

Complies with

Additional activities performed in accordance with the Mercedes-Benz AG guidelines

Completed

Service Report 2

Mercedes-Benz Mercedes [redacted] szawa Sp. with Date 26.09.2012
 o.o.; M [redacted]
 ul. Got [redacted] Repair Order No. 31 [redacted] 8
 Warsaw Run 39053 km

Serviced

Service Service B
 Workshop code 606
 Time Remaining 165 Days
 Remaining mileage 1200 km

Oil quality/viscosity

Description Engine oil
 Viscosity MB
 ' 229.51

Additional work

Air filter cartridge replacement
 Engine: filter and oil replacement motor

For next review

Mercedes-Benz
 No corrosion guarantee perforation

Interval compatible with guidelines of Mercedes-Benz AG

Complies with

Additional activities performed in accordance with the Mercedes-Benz AG guidelines

Completed



Service Report 1

Mercedes-Benz

Mercedes-Benz S.A. Szwawa Sp.
z o.o.
ul. G.
Warszawa

Date 08.03.2012

Repair Order No. 3168

Run 20284 km

Serviced

Service Service A
Workshop code 505
Time Remaining 120 Days
Remaining mileage 0 km

Oil quality/viscosity

Description Engine oil
Viscosity 229.51

Additional work

Air filter cartridge replacement
Engine: replacement of filter and engine oil

For next review

Mercedes-Benz
Warranty for no perforation corrosion

Interval according to Mercedes-Benz AG guidelines

Complies with

Additional operations carried out in accordance with the guidelines of Mercedes-Benz AG

Completed



istoric-service.ro



Vehicle information (History of damage)

08301

FIN: WDD [redacted] 202

Current vehicle guidelines:

none

Open service actions:



Code damaged a	Description	Date terminated a	Status shares	KDM-Type	Days to terminated a
5497507	20P5497507		Active	Recall	0

Decisions of ESKULAB:
History of damage:

Type	Date acc.	X	#	Code damaged a	Corruption code description	Application No	Code country du	Market	LL	M	E	Note No. Un.	Note date Un.
	04.02.2011 6				Small service - Regular reviews	16161471	559	00001	137130	km			
	16.03.2011 5				Large service - Regular reviews	61653439	559	07900	115396	km			
	13.03.2011 5	AA	35	000011SV 7	Large scope of review/ Review B Agreement service	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	13.03.2011 5	AB	34	009102SV 7	Air filter cartridge Service Contract	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	13.03.2011 5	AC	33	083108SV 7	Air Filter/Filter antipollen system heating/ventilation Service Contract	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	13.03.2011 5		32	082A2353 7	Windscreen wiper blade front left Not sufficient performance	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	13.03.2011 5		31	082063SV 7	Wiper blade at the back Service Contract	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	13.03.2011 5		30	042101D1 7	Brake disk with front Consumption	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	13.03.2011 5		29	042201D1 7	Rear brake disk Consumption	48990	559	07900	115396	km	0	00000000 0	03.04.2015
	25.06.2011 4				Small service - Regular reviews	51658433	559	07900	95245	km			
	24.06.2011 4	AD	28	000012SV 7	Small scope of review/ review A Agreement service	45937	559	07900	95245	km	0	00000000 0	27.06.2014
	24.06.2011 4	AB	27	009102SV 7	Air filter cartridge Service Contract	45937	559	07900	95245	km	0	00000000 0	27.06.2014
	24.06.2011 4	AC	26	083108SV 7	Air Filter/Filter antipollen system heating/ventilation Service Contract	45937	559	07900	95245	km	0	00000000 0	27.06.2014
	24.06.2011 4		25	043051367	Vacuum pump Noise	45937	559	07900	95245	km	0	00000000 0	27.06.2014
	22.10.2011 3	AA	24	000011SV 7	Large scope of review/ Review B Agreement service	43261	559	07900	77028	km	0	00000000 0	25.10.2013





Vehicle information (History of damage)

08301

Type	Date acc.	X	#	Code damaged a	Corruption code description	Application No	Code country du	Market	LL	M	E	Note No. Un.	Note date Un.
	22.10.2011 3	AB	23	009102SV 7	Air filter cartridge Service Contract	43261	559	07900	77028	km	0	00000000 0	25.10.2013
	22.10.2011 3		22	047028SV 7	Water separator in fuel system Service Contract	43261	559	07900	77028	km	0	00000000 0	25.10.2013
	22.10.2011 3		21	043000SV 7	fluid replacement Contract service	43261	559	07900	77028	km	0	00000000 0	25.10.2013
	22.10.2011 3	AC	20	083108SV 7	Air Filter/Filter antipollen system heating/ventilation Service Contract	43261	559	07900	77028	km	0	00000000 0	25.10.2013
	22.10.2011 3	AE	19	007921427		43261	559	07900	77028	km	0	00000000 0	25.10.2013
	22.10.2011 3		18	054687908	Control Module Parktronic Version software	43261	559	07900	77028	km	0	00000000 0	25.10.2013
	22.10.2011 3				Large service - Regular reviews	41664280	559	07900	77028	km			
	24.04.2011 3	AD	17	000012SV 7	Small scope of review/ review A Agreement service	35590	559	04300	58979	km	0	00000000 0	26.04.2013
	24.04.2011 3	AB	16	009102SV 7	Air filter cartridge Service Contract	35590	559	04300	58979	km	0	00000000 0	26.04.2013
	24.04.2011 3		15	077300SV 8	Cleaning/ window lubrication roofing service	35590	559	04300	58979	km	0	00000000 0	26.04.2013
	24.04.2011 3		14	042114D1 7	Brake lining with front Consumption	35590	559	04300	58979	km	0	00000000 0	26.04.2013
	24.04.2011 3		13	042214D1 7	Brake lining at the rear Consumption	35590	559	04300	58979	km	0	00000000 0	26.04.2013
	24.04.2011 3		12	08204X01 8	Data update system maps Navigation additional	35590	559	04300	58979	km	0	00000000 0	26.04.2013
	24.04.2011 3				Small service - Regular reviews	35590	559	04300	58979	km			
	17.12.2011 2		11	050207387	Flexible band fluid cooling loosening	39647	559	07900	46388	km	0	00000000 0	04.01.2013
	17.12.2011 2		10	059902368		39647	559	07900	46388	km	0	00000000 0	04.01.2013
	26.09.2011 2	AF	9	001215047	connection port cylinder head leak	38605	559	07900	39053	km	0	00000000 0	28.09.2012
	26.09.2011 2	AF	8	001215M3 8	connection port cylinder head Receive and deliver repaired vehicle	38605	559	07900	39053	km	0	00000000 0	28.09.2012
	26.09.2011 2	AA	7	000011SV 7	Large scope of review/ Review B Agreement service	40524	559	07900	39053	km	0	00000000 0	29.03.2013
	26.09.2011 2	AB	6	009102SV 7	Air filter cartridge Service Contract	40524	559	07900	39053	km	0	00000000 0	29.03.2013
	26.09.2011 2	AC	5	083108SV 7	Air Filter/Filter antipollen system heating/ventilation Service Contract	40524	559	07900	39053	km	0	00000000 0	29.03.2013
	26.09.2011 2				Large service - Regular reviews	31663508	559	07900	39053	km			
	08.03.2011 2	AE	4	007921257		36279	559	07900	20284	km	0	00000000 0	16.03.2012

Vehicle information (History of damage)

08301

Type	Date acc.	X	#	Code damaged a	Corruption code description	Application No	Code country du	Market	LL	M	E	Note No. Un.	Note date Un.
	08.03.2011 2	AA	3	000011SV 7	Large scope of review/ Review B Agreement service	40523	559	07900	20284	km	0	00000000 0	29.03.2013
	08.03.2011 2	AB	2	009102SV 7	Air filter cartridge Service Contract	40523	559	07900	20284	km	0	00000000 0	29.03.2013
	08.03.2011 2	AC	1	083108SV 7	Air Filter/Filter antipollen system heating/ventilation Service Contract	40523	559	07900	20284	km	0	00000000 0	29.03.2013
	08.03.2011 2				Small service - Regular reviews	31653338	559	07900	20284	km			



FIN: WDD[]202

Database:

FIN: WD[]202

Market: MBPL

VIN:

Date and room register: 20.06.2011

Registration No: WK3[]

Customer #:

Date of manufacture: 19.05.2011

Warranty Start: 20.06.2011

Model: E 250 CDI 4MATIC

Seller:

Year of production: 2011

Last observed mileage: 115396 km

Radio Lot: B4[]

Location: normally

Unit:

Typ e	Unit No.	Des cription
01	65[]542	Engine
02	722[]707	Transmission

Vehicle info:

- The vehicle is provided with extended service. Every vehicle visit to the Authorized Service Station should be reported to the Mercedes-Benz Leasing [] Service Center at telephone number (+4[]) 88 from Monday to Friday from 8.00 to 18.00 and on Saturdays from 8.00 to 13.00.

Customer Address:



FIN: WDD 202

SA-codes:

Code	Text
A22	
A36	
A49	
A86	
A89	
B12	Tire-change toolkit
D0A	
D0C	
D0D	
FS	STATION WAGON
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
J81	RELEASE JUNE
K10	Software control for the active light function
K11	Adaptive brake lights
K14	
L	L.H.D.
M22	CAPACITY 2.2 LITERS
Q35	Light Package
P54	Anti-Theft Protection package
R01	Summer tyres
R15	43.2 cm (17-inch) 10-twin-spoke light-alloy wheels
U01	Rear belt status indication in the instrument disp
German submarine U41	Fuel/water separator and lubrication package
German submarine U60	Active Bonnet
German submarine U72	DVD-PLAYER WITH REGIONAL-CODE 2 EUROPE, JAPAN
VL	FRONT AXLE HALF SHAFT, LEFT
VR	FRONT AXLE HALF SHAFT, RIGHT
V73	
03O	
051	AEJ 10/2
1U2	Snow guard for air conditioning air intake
108	black / alpaca gray ARTICO man-made leather
182	CONVERTER WITH DEV. CHARACTERISTIC
200	LEATHER
205	Literature in English
211	Direct control system

Vehicle information (SA-code)

 08

Code	Text
230	PARRONIC
240	LED daytime running lights
255B	
287	EASY-PACK quickfold
291	Pelvis
294	Kneebag
298	Rear Seat Safety package
401	Climatic front seats
413	Panoramic sliding sunroof electric, in glass
427	AMG SPEEDSHIFT MCT 7G-TRONIC
474	Diesel private filter
477	Tire pressure loss warning system
485	DIRECT CONTROL suspension comfortably
5XX	EUROPE
518	Media Interface
527	COMAND Online incl. DVD
55U	Roof liner beige fabric
551	Anti-theft alarm system
559	POLAND
580	THERMATIC automatic climate control
600	Headlamp cleaning system
608	Adaptive Highbeam Assist
619	Cornering light function
622	Intelligent Light System
682	Extinguisher
690	Collapsible spare wheel instead of TIREFIT tire se
700	
731	Trim elements brown burr walnut wood gloss
801	Technical modifications
81P	
840	Heat-insulating dark-tinted glass
882	Interior monitoring system
928	EU5 emission standard
955	ELEGANCE
963	Light clinging
966	COC document EU5 without registration certificate


RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIAȚIAT | DIRECT DIN REPREZENTANȚA
