

RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIAT | DIRECT DIN REPREZENTANTA



Mercedes-Benz

Caiet de Service Digital (Istoric service)

Acest raport contine urmatoarele inregistrari:

Service 7	04.02.2016
Service 6	16.03.2015
Service 5	25.06.2014
Service 4	22.10.2013
Service 3	24.04.2013
Service 2	26.09.2012
Service 1	08.03.2012



Istoricul de sevice a fost printat de catre:



Mercedes-Benz

Semnatura / stampila atelierului

Raport oficial MERCEDES din reprezentanta



**Caiet de Service Digital****Date vehicul**

Vehicul E 250 CDI 4MATIC
Prima inmatriculare 20.06.2011
FIN WDE [redacted] 202

Urmatoarea 02.2017 Urmatoarea inspectie ITP 06.2016
Revizie 157130 km
(in functie de ce are loc prima data)

Raport de revizii 7

Mercedes-Benz Mercedes [redacted] p. z o.o. Data 04.02.2016
ul. Got [redacted] Nr. comanda atelier 161 [redacted]
Warsza [redacted] Rulaj 137130 km

Revizie executata

Revizie Revizie A
Cod revizie GD0V
Timp ramas 40 Zile
Distanța ramasa -1700 km

Calitate/Vascozitate ulei

Descriere Ulei motor
Calitate ulei 229.51
Vascozitate 5W-30

Descriere Cutie de viteze automata
Calitate ulei 236.15
Vascozitate

Lucrari suplimentare

Inlocuit filtru praf clima
Inlocuit element filtru aer
Inlocuit ulei si filtru ulei cutie viteze automata
Inlocuit ulei si filtru ulei
Inlocuit lichid de frana

Pana la urmatoarea revizie

Mobilitate Mercedes-Benz
Garantie coroziune prin perforare

Interval revizii conform specific. Mercedes-Benz AG

Conform cu

Op. suplimentare

efectuat





Raport de revizii 6

Mercedes-Benz

Merced [redacted] Sp. z o.o.
ul. Gott [redacted]
Warsza [redacted]

Data 16.03.2015
Nr. comanda atelier 616 [redacted]
Rulaj 115396 km

Revizie executata

Revizie Revizie B
Cod revizie 860E
Timp ramas 100 Zile
Distanta ramasa -100 km

Calitate/Vascozitate ulei

Descriere Ulei motor
Calitate ulei 229.51
Vascozitate 0W-30

Lucrari suplimentare

Inlocuit placute/saboti frana
punte fata
Inlocuit placute/saboti frana
punte spate
Inlocuit filtru praf clima
Inlocuit element filtru aer
Inlocuit ulei si filtru ulei

Pana la urmatoarea revizie


Mobilitate Mercedes-Benz
Garantie coroziune prin perforare

Interval revizii conform specific. Mercedes-Benz AG

Conform cu

Op. suplimentare

efectuat





Raport de revizii 5

Mercedes-Benz

Mercedes
ul. Gottli
Warszaw

p. z o.o.

Data

25.06.2014

Nr. comanda atelier

516

Rulaj

95245 km

Revizie executata

Revizie Revizie A
Cod revizie 505
Timp ramas 120 Zile
Distanta ramasa 1800 km

Calitate/Vascozitate ulei

Descriere Ulei motor
Calitate ulei
Vascozitate 5W-30

Lucrari suplimentare

Inlocuit filtru praf clima
Inlocuit element filtru aer
Inlocuit ulei si filtru ulei


Pana la urmatoarea revizie

Mobilitate Mercedes-Benz
Garantie coroziune prin perforare

Interval revizii conform specific. Mercedes-Benz AG

Conform cu

Op. suplimentare
efectuat





Raport de revizii 4

Mercedes-Benz

Merced
ul. Gott
Warszav

p. z o.o.

Data

22.10.2013

Nr. comanda atelier

416

Rulaj

77028 km

Revizie executata

Revizie Revizie B
Cod revizie 5E0K
Timp ramas 185 Zile
Distanta ramasa 2000 km

Calitate/Vascozitate ulei

Descriere Ulei motor
Calitate ulei 229.51
Vascozitate 5W-30

Lucrari suplimentare

Inlocuit element filtru aer
Inlocuit filtru combustibil
Inlocuit ulei si filtru ulei
Inlocuit lichid de frana

Pana la urmatoarea revizie


Mobilitate Mercedes-Benz
Garantie coroziune prin perforare

Interval revizii conform specific. Mercedes-Benz

AG
Conform cu

Op. suplimentare

efectuat



Raport oficial MERCEDES din reprezentanta





Raport de revizii 3

Mercedes-Benz

Zbigniewowski
ul. Eu
Warsz

Data 24.04.2013
Nr. comanda atelier 355
Rulaj 58979 km

Revizie executata

Revizie Revizie A
Cod revizie 850D
Timp ramas 155 Zile
Distanta ramasa 100 km

Calitate/Vascozitate ulei

Descriere Ulei motor
Calitate ulei 229.51
Vascozitate MB

Lucrari suplimentare

Inlocuit placute/saboti frana
punte fata
Inlocuit placute/saboti frana
punte spate
Inlocuit element filtru aer
Inlocuit ulei si filtru ulei

Pana la urmatoarea revizie


Mobilitate Mercedes-Benz
Garantie coroziune prin perforare

**Interval revizii conform specific. Mercedes-Benz
AG**

Conform cu

Op. suplimentare

efectuat



**Raport de revizii 2**

Mercedes-Benz

Merced
MBW
ul. Go
Warsz

p. z o.o.;

Data 26.09.2012

Nr. comanda atelier 316

Rulaj 39053 km

Revizie executataRevizie Revizie B
Cod revizie 606
Timp ramas 165 Zile
Distanta ramasa 1200 km**Calitate/Vascozitate ulei**Descriere Ulei motor
Calitate ulei 229.51
Vascozitate MB**Lucrari suplimentare**Inlocuit element filtru aer
Inlocuit ulei si filtru ulei **Pana la urmatoarea revizie**Mobilitate Mercedes-Benz
Garantie coroziune prin perforare **Interval revizii conform specific. Mercedes-Benz AG**Conform cu **Op. suplimentare**
efectuat **Raport de revizii 1**

Mercedes-Benz

Merced
ul. Gott
Warsz

p. z o.o.

Data 08.03.2012

Nr. comanda atelier 316

Rulaj 20284 km

Revizie executataRevizie Revizie A
Cod revizie 505
Timp ramas 120 Zile
Distanta ramasa 0 km**Calitate/Vascozitate ulei**Descriere Ulei motor
Calitate ulei 229.51
Vascozitate**Lucrari suplimentare**Inlocuit element filtru aer
Inlocuit ulei si filtru ulei **Pana la urmatoarea revizie**Mobilitate Mercedes-Benz
Garantie coroziune prin perforare **Interval revizii conform specific. Mercedes-Benz AG**Conform cu **Op. suplimentare**
efectuat 



FIN: WDD[]202

Current advice for the vehicle:

- ESKULAB request necessary due to special warranty

Outstanding KDM:

Damage code	Description	End date	Campaign state	KDM-Type	Days to Expire
5497507	20P54[]		Active	Recall	0

ESKULAB decisions:**Damage history:**

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	04.02.2016				Service minor - regelm. Wartung	16161471	559	00001	137130	km			
	16.03.2015				Service major - regelm. Wartung	61653439	559	07900	115396	km			
	13.03.2015	AA	35	000011SV7	Major service scope/Service B Service contract	48990	559	07900	115396	km	0	000000000	03.04.2015
	13.03.2015	AB	34	009102SV7	Air filter element Service contract	48990	559	07900	115396	km	0	000000000	03.04.2015
	13.03.2015	AC	33	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	48990	559	07900	115396	km	0	000000000	03.04.2015
	13.03.2015		32	082A23537	Wiper blade, front, left Insufficient effect/power	48990	559	07900	115396	km	0	000000000	03.04.2015
	13.03.2015		31	082063SV7	Windshield wiper blade, rear Service contract	48990	559	07900	115396	km	0	000000000	03.04.2015
	13.03.2015		30	042101D17	Brake disc, front Worn	48990	559	07900	115396	km	0	000000000	03.04.2015
	13.03.2015		29	042201D17	Brake disc, rear Worn	48990	559	07900	115396	km	0	000000000	03.04.2015
	25.06.2014				Service minor - regelm. Wartung	51658433	559	07900	95245	km			
	24.06.2014	AD	28	000012SV7	Minor service scope/Service A Service contract	45937	559	07900	95245	km	0	000000000	27.06.2014
	24.06.2014	AB	27	009102SV7	Air filter element Service contract	45937	559	07900	95245	km	0	000000000	27.06.2014
	24.06.2014	AC	26	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	45937	559	07900	95245	km	0	000000000	27.06.2014
	24.06.2014		25	043051367	Vacuum pump Noise	45937	559	07900	95245	km	0	000000000	27.06.2014
	22.10.2013	AA	24	000011SV7	Major service scope/Service B Service contract	43261	559	07900	77028	km	0	000000000	25.10.2013
	22.10.2013	AB	23	009102SV7	Air filter element Service contract	43261	559	07900	77028	km	0	000000000	25.10.2013
	22.10.2013		22	047028SV7	Water separator, fuel system Service contract	43261	559	07900	77028	km	0	000000000	25.10.2013
	22.10.2013		21	043000SV7	Brake fluid change Service contract	43261	559	07900	77028	km	0	000000000	25.10.2013
	22.10.2013	AC	20	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	43261	559	07900	77028	km	0	000000000	25.10.2013
	22.10.2013	AE	19	007921427	1205P07B22	43261	559	07900	77028	km	0	000000000	25.10.2013
	22.10.2013		18	054687908	Control unit, Parktronic system Software status	43261	559	07900	77028	km	0	000000000	25.10.2013



Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	22.10.2013				Service major - regelm. Wartung	41664280	559	07900	77028	km			
	24.04.2013	AD	17	000012SV7	Minor service scope/Service A Service contract	35590	559	04300	58979	km	0	000000000	26.04.2013
	24.04.2013	AB	16	009102SV7	Air filter element Service contract	35590	559	04300	58979	km	0	000000000	26.04.2013
	24.04.2013		15	077300SV8	Clean/lubricate sliding roof Service contract	35590	559	04300	58979	km	0	000000000	26.04.2013
	24.04.2013		14	042114D17	Brake lining, front Worn	35590	559	04300	58979	km	0	000000000	26.04.2013
	24.04.2013		13	042214D17	Brake lining, rear Worn	35590	559	04300	58979	km	0	000000000	26.04.2013
	24.04.2013		12	08204X018	Map data update, navigation system Follow-up operations	35590	559	04300	58979	km	0	000000000	26.04.2013
	24.04.2013				Service minor - regelm. Wartung	35590	559	04300	58979	km			
	17.12.2012		11	050207387	Hose clip, coolant hose Loose	39647	559	07900	46388	km	0	000000000	04.01.2013
	17.12.2012		10	059902368	1204P59A93	39647	559	07900	46388	km	0	000000000	04.01.2013
	26.09.2012	AF	9	001215047	Connection fitting, cylinder head Leaks	38605	559	07900	39053	km	0	000000000	28.09.2012
	26.09.2012	AF	8	001215M38	Connection fitting, cylinder head Pickup and delivery service	38605	559	07900	39053	km	0	000000000	28.09.2012
	26.09.2012	AA	7	000011SV7	Major service scope/Service B Service contract	40524	559	07900	39053	km	0	000000000	29.03.2013
	26.09.2012	AB	6	009102SV7	Air filter element Service contract	40524	559	07900	39053	km	0	000000000	29.03.2013
	26.09.2012	AC	5	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	40524	559	07900	39053	km	0	000000000	29.03.2013
	26.09.2012				Service major - regelm. Wartung	31663508	559	07900	39053	km			
	08.03.2012	AE	4	007921257	1106P07B40	36279	559	07900	20284	km	0	000000000	16.03.2012
	08.03.2012	AA	3	000011SV7	Major service scope/Service B Service contract	40523	559	07900	20284	km	0	000000000	29.03.2013
	08.03.2012	AB	2	009102SV7	Air filter element Service contract	40523	559	07900	20284	km	0	000000000	29.03.2013
	08.03.2012	AC	1	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	40523	559	07900	20284	km	0	000000000	29.03.2013
	08.03.2012				Service minor - regelm. Wartung	31653338	559	07900	20284	km			





FIN: WDD[]202

Warranty & Service:

Service type	Code	Start date	End date	Start-LL	End-LL	Sales. Dealer	Active	Contract No.
service contract	P_EXC	20.06.2011	10.10.2015	0	[]273		No	0010[]

Description of special coverage:

EXCELLENT PC

Passenger Car:

- warranty for whole car

- maintenance

- wear

Generally included options:

- towing

- refill engine oil between maintenance

Selectable options - check EVA!

Contract informaton:

OIL_SER;TOWING;

Element of service contract:

Market:

MBPL

Contract number:

001001/0197

Customer name:

MERCEDES-BENZ LEASING []AWA

Contract status:

service contract / vehicle terminated date

Pickup/Delivery service:

not allowed

Towing:



Replacement vehicle / Mobility:

not allowed

Car wash:

not allowed

Oil refill between services:

allowed

Number of tyres:

keine Reifen

Usage:

Short Distance

Product line:

Excellent





FIN: WDD[]202

Master data:

FIN: WDD[]202

VIN:

Characteristics: WK3[]

Production date: 19.05.2011

Model: E 250 CDI 4MATIC

Model year: 2011

Radio serial no.: B41[]

Market: MBPL

Registration date: 20.06.2011

Customer number:

Warranty start date: 20.06.2011

Selling dealer:

Last known mileage: 115396 km

Vehicle status: normal

Components:

Type	Component no	Description
01	65[]42	Engine
02	72[]07	Transmission

Vehicle information:

- The vehicle is provided with extended service. Every vehicle visit to the authorized service station should be reported to the Mercedes - Benz Leasing [] Center at telephone number (+4[]8 from Monday to Friday from 8.00 to 18.00 and on Saturdays from 8.00 to 13.00.





FIN: WDD [] 202

Option-CODE:

Code	Text
A22	
A36	
A49	
A86	
A89	
B12	Tyre-change toolkit
D0A	
D0C	
D0D	
FS	STATION WAGON
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
J81	RELEASE JUNE
K10	Software control for the active light function
K11	Adaptive brake lights
K14	
L	L.H.D
M22	CAPACITY 2.2 LITRE
P35	Light Package
P54	Anti-Theft Protection package
R01	Summer tyres
R15	43.2 cm (17-inch) 10-twin-spoke light-alloy wheels
U01	Rear belt status indication in the instrument disp
U41	Fuel/water separator and lubrication package
U60	Active Bonnet
U72	DVD-PLAYER WITH REGIONAL-CODE 2 EUROPE,JAPAN
VL	FRONT AXLE HALF SHAFT, LEFT
VR	FRONT AXLE HALF SHAFT, RIGHT
V73	
030	
051	AEJ 10/2
1U2	Snow guard for air conditioning air intake
108	black / alpaca grey ARTICO man-made leather
182	CONVERTER WITH DEV. CHARACTERISTIC
200	LEATHER
205	Literature in English
211	Direct-steer system



Code	Text
230	PARKTRONIC
240	LED-daytime running lights
255B	
287	EASY-PACK quickfold
291	Pelvis airbag
294	Kneebag
298	Rear Seat Safety package
401	Climatised front seats
413	Panoramic sliding sunroof electric, in glass
427	AMG SPEEDSHIFT MCT 7G-TRONIC
474	Diesel particulate filter
477	Tyre pressure loss warning system
485	DIRECT CONTROL suspension comfortably
5XX	EUROPE
518	Media Interface
527	COMAND Online incl. DVD
55U	Roof liner beige fabric
551	Anti-theft alarm system
559	POLAND
580	THERMATIC automatic climate control
600	Headlamp cleaning system
608	Adaptive Highbeam Assist
619	Cornering light function
622	Intelligent Light System
682	Fire extinguisher
690	Collapsible spare wheel instead of TIREFIT tyre se
700	
731	Trim elements brown burr walnut wood gloss
801	Technical modifications
81P	
840	Heat-insulating dark-tinted glass
882	Interior monitoring system
928	EU5 emission standard
955	ELEGANCE
963	Flashing light clinging
966	COC document EU5 without registration certificate



Data card: WDD[]202

Vehicle datacard

Vehicle identification number (VIN) WDD[]202
 Vehicle model E 250 CDI 4MATIC BlueEFFICIENCY Wagon
 Order number 015[]4
 Production number 757[]
 Production plant P0500
 Shipment date 24.05.11
 EC approval number e1*200[]7
 EC approval date 15.11.10

Major assemblies

	Major assembly number	Variant	Object number
Engine	65[]542		A6[]48
Transmission	72[]707		214[]4
All-wheel front axle transmission	221[]91		22[]2
Front axle, left	212[]0599		
Front axle, right	212[]0606		
Rear axle	212[]005		
Steering	212[]2732		2[]00

Codes

Code	Designation	Code type
030	No code designations currently available	sales
051	AEJ 10/2	sales
108	No code designations currently available	sales
182	No code designations currently available	production
1U2	Snow guard for air conditioning air intake	sales
200A	Leather upholstery	sales
205A	No code designations currently available	sales
211	STEER CONTROL Steering-Assist	sales
230	PARKTRONIC incl. Parking Guidance	sales
240	LED-Tagfahrlicht	sales
255B	No code designations currently available	partsIdent
275B	No code designations currently available	partsIdent
287	EASY-PACK through-loading facility	sales
291	Pelvis airbag	sales
294	Kneebag driver's side	sales
298	Rear Seat Safety package	sales





Code	Designation	Code type
302B	No code designations currently available	partsIdent
332B	No code designations currently available	partsIdent
401	Climatised front seats (heated and ventilated)	sales
413	Full glass roof with sunroof	sales
427	7-speed automatic transmission	sales
474	Diesel Particulate filter	sales
477	Tyre pressure loss warning system	sales
485	Comfort-tuned suspension	sales
518	Media Interface including consumer cable set	sales
527	COMAND APS multimedia system	sales
551	Anti-theft warning system	sales
559L	Poland	sales
55U	Roof liner fabric beige	sales
580	Automatic air conditioning (THERMATIC)	sales
5XXL	No code designations currently available	sales
600	Headlamp cleaning system	sales
608	Adaptive Highbeam Assist	sales
619	Cornering light function	sales
622	Intell. Light System w. bi-xenon (LHD veh.)	sales
682	Fire extinguisher installed	sales
690	Emergency wheel (mini spare)	sales
700	No code designations currently available	sales
731	Wood finish, burr walnut trim	sales
801	Technical modifications	sales
81P	CONTROL CODE SALES	sales
840	Dark-tinted rear windscr./rear side windows	sales
882	Interior motion sensor	sales
928	Emission control system with Euro 5 technology	sales
955	ELEGANCE	sales
963U	No code designations currently available	sales
966	CoC document EU5 without Reg. Cert. Part II	sales
A22	No code designations currently available	production
A36	No code designations currently available	production





Code	Designation	Code type
A49	No code designations currently available	production
A86	No code designations currently available	production
A89	Friction-reduced	production
B12	Tyre-change tool kit	sales
D0A	No code designations currently available	sales
D0C	No code designations currently available	sales
D0D	No code designations currently available	sales
F212	No code designations currently available	partsIdent
FS	Crewbus	partsIdent
G965	No code designations currently available	partsIdent
GA	No code designations currently available	partsIdent
HA	No code designations currently available	partsIdent
J81	No code designations currently available	production
K10	Software control for the active light function	sales
K11	Adaptive brake light, flashing	sales
K14	No code designations currently available	sales
L	No code designations currently available	partsIdent
M005	4MATIC	partsIdent
M014	No code designations currently available	partsIdent
M22	No code designations currently available	production
M651	No code designations currently available	partsIdent
P35	Light Package	sales
P54	Anti-Theft Protection package	sales
R01	Summer tyres	sales
R15	10-spoke light-alloy wheels 43.2 cm (17")	sales
U01	Belt buckle with switch	sales
U41	Fuel/water separator and lubrication package	sales
U60	Active Bonnet (Pedestrian protection)	sales
U72	No code designations currently available	sales
V73	No code designations currently available	sales
VL	No code designations currently available	partsIdent
VR	No code designations currently available	partsIdent

Equipment





Mercedes-Benz

Paints

Interior equipment 205 -

Additional information on interior equipment 200 - Leather upholstery

Paint

Use	Code	Additional paint information	Designation
Paintwork 1	963		

Tires

Tire manufacturer CONTINENTAL CONTINENTAL

Genuine major assembly

Factory engine number 65 42

Factory engine item number A6

Factory transmission number 72 07

Factory transmission item number 21



Raport oficial MERCEDES din reprezentanta



RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIIAT | DIRECT DIN REPREZENTANTA

