

RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIIAT | DIRECT DIN REPREZENTANTA



PORSCHE



Vehicle identification number (VIN) WPD[redacted]538

Order type Panamera 4S Diesel (97ADD1)

Model year 2017



There are open campaigns for this vehicle.

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCSS job management (PGIS) are available. This information may not be transmitted to third parties.

Total warranty repair days (WRD): 28 Day(s)

Filter settings

Campaign
 Repair
 Maintenance/Inspection
 Documentation

Reset Filter

Collapse all

Status Repair Start Repair End Dealer Mileage DMS order number

	30.11.2021	30/11/2021	115 [redacted]	164678 km	202 [redacted]	1		
	General workshop visit / Service (DMS)							
	20/10/2021	21/10/2021	115 [redacted]	158342 km		1		
	Other: diverse Fehler							
	19/05/2021	01/06/2021	784 [redacted]	153898 km	211 [redacted]	1		
	General workshop visit / Service (DMS):*							



PORSCHE

Filter settings

Campaign Repair Maintenance/Inspection Documentation

Reset Filter

	09/04/2021	21/04/2021	784 <input type="text"/>	151449 km	211 <input type="text"/>	1		
			General workshop visit / Service (DMS): *					
	22/03/2021	22/03/2021	784 <input type="text"/>	149650 km	211 <input type="text"/>	1		
			General workshop visit / Service (DMS): *					
	24/02/2021	24/02/2021	784 <input type="text"/>	149623 km	211 <input type="text"/>	1		
			General workshop visit / Service (DMS): *					
	03/02/2021	08/02/2021	784 <input type="text"/>	147904 km	211 <input type="text"/>	1		
			Location: 43010 Level control Symptom: 1611 No function					
	26/01/2021	26/01/2021	784 <input type="text"/>	147738 km	211 <input type="text"/>	1		
			General workshop visit / Service (DMS): *					
	12/11/2020	12/11/2020	784 <input type="text"/>	144521 km	201 <input type="text"/>	1		
			General workshop visit / Service (DMS): *					
	23/10/2020	23/10/2020	784 <input type="text"/>	130000 km	201 <input type="text"/>	1		
			Location: Campaign complete: WLA81 Cardan flange / Check all-wheel final drive and replace if necessary Symptom: 6600 Workshop campaign					



PORSCHE

Filter settings

Campaign Repair Maintenance/Inspection Documentation

Reset Filter

05/06/2020 22/06/2020 784 129690 km 202 1

Repair

Location: 43160 Control unit for chassis control
Symptom: 1613 No function occasionally

20/02/2020 21/02/2020 784 122635 km 202 2

Campaign

Location: Campaign complete: WJ203 Replacing PASM control unit
Symptom: 6600 Workshop campaign

Maintenance/Inspection

Major maintenance

02/01/2020 09/01/2020 784 117895 km 202 3

Campaign

Location: Campaign complete: WKA11 Replace fuel return lines
Symptom: 6600 Workshop campaign

Campaign

Location: Campaign complete: AKB01 Replace suction hoses and re-program DME and PDK control unit
Symptom: 9900 Recall campaign

Repair

Location: 19550 Coolant regulator housing
Symptom: 1611 No function

20/12/2019 20/12/2019 784 116416 km 201 5

Campaign

Location: Campaign not feasible: WKA12 Replace fuel return lines
Symptom: 6600 Workshop campaign

Campaign

Location: Campaign complete: AKB81 Re-programming instrument cluster
Symptom: 9900 Recall campaign

Campaign

Location: Campaign complete: WKK21 Re-program RDK control unit
Symptom: 6600 Workshop campaign

Campaign

Location: Campaign not feasible: AKB0Z Replace suction hoses and re-program DME and PDK control unit
Symptom: 9900 Recall campaign

Repair

Location: 55870 Rear lock, upper part
Symptom: 1622 Does not close




PORSCHE

Filter settings

Campaign Repair Maintenance/Inspection Documentation

Reset Filter

	04/10/2019	04/10/2019	784 <input type="text"/>	104000 km	201 <input type="text"/>	1			
	General workshop visit / Service (DMS)								
	01/10/2019	02/10/2019	784 <input type="text"/>	103578 km	201 <input type="text"/>	1			
		Location: Campaign complete: WKJ01 Re-programming air-conditioning control unit Symptom: 6600 Workshop campaign							
	27/06/2019	27/06/2019	784 <input type="text"/>	97475 km	201 <input type="text"/>	1			
	General workshop visit / Service (DMS): ESTENSIONE GARANZIA								
	07/05/2019	07/05/2019	784 <input type="text"/>	92202 km	2019 <input type="text"/>	1			
	General workshop visit / Service (DMS): MANUTENZIONE SOST.OLIO FRENI								
	08/04/2019	15/04/2019	784 <input type="text"/>	89716 km	201 <input type="text"/>	2			
			Location: Campaign complete: AKA11 Re-programming instrument cluster Symptom: 9900 Recall campaign						
				Location: 26900 NOx sensor Symptom: 4000 Electrical faults					
	29/03/2019	29/03/2019	784 <input type="text"/>	89308 km	2019 <input type="text"/>	1			
	General workshop visit / Service (DMS): spia freni accesa								



PORSCHE

Filter settings

Campaign Repair Maintenance/Inspection Documentation

Reset Filter

22/01/2019 22/01/2019 784 78000 km 20 2

		Location: Campaign complete: AJ131 Re-programming control unit for electric power steering Symptom: 9900 Recall campaign
		Location: Campaign complete: WJ891 Change vehicle order in instrument cluster Symptom: 6600 Workshop campaign

19/11/2018 22/11/2018 784 76861 km 2


		Location: Campaign not feasible: WJ89Z Change vehicle order in instrument cluster Symptom: 6600 Workshop campaign
		Location: 43150 Compressor for levelling system Symptom: 1713 Seized up

08/10/2018 08/10/2018 784 71612 km 2

		Location: Campaign complete: WJ611 Check filler flap / charge port door and replace if necessary Symptom: 6600 Workshop campaign
		Location: 70570 A-pillar trim panel Symptom: 1817 Loose

05/09/2018 06/09/2018 784 68417 km 2

		Location: 72160 Covering Symptom: 3018 Fault in leather characteristic, leather structure
		Location: 43150 Compressor for levelling system Symptom: 5000 Leaks



PORSCHE

Filter settings

Campaign Repair Maintenance/Inspection Documentation

Reset Filter

19/06/2018 21/06/2018 784 62120 km 2 🔍 ^

Maintenance/Inspection

Major maintenance

Repair



Location: 26840 Reducing agent supply line
Symptom: 5000 Leaks

13/03/2018 16/03/2018 784 48000 km 3 🔍 ^

Repair



Location: 46380 Brake pad rear
Symptom: 1824 Severe wear

Repair



Location: 64120 Windshield
Symptom: 1521 Crack/fissure

Repair



Location: 46360 Brake pad front
Symptom: 1824 Severe wear

13/03/2018 15/03/2018 784 48168 km 4 🔍 ^

Campaign



Location: Campaign complete: WH291 Re-programming PASM control unit
Symptom: 6600 Workshop campaign

Campaign




Location: Campaign complete: WJ051 Re-code front camera control unit
Symptom: 6600 Workshop campaign

Campaign



Location: Campaign complete: WH561 Rework ground cable attachment
Symptom: 6600 Workshop campaign

Repair



Location: 26840 Reducing agent supply line
Symptom: 5000 Leaks

05/10/2017 05/10/2017 784 31587 km 1 🔍 ^

Maintenance/Inspection

Major maintenance



PORSCHE

Filter settings

Campaign Repair Maintenance/Inspection Documentation

Reset Filter

		20/09/2017	20/09/2017	784 <input type="text"/>	28722 km	3		
			Location:	Campaign complete: WH171 Replace front right power window				
			Symptom:	6600 Workshop campaign				
			Location:	Campaign complete: WH301 Re-programming the airbag control unit				
			Symptom:	6600 Workshop campaign				
			Location:	Campaign complete: WH191 Rework routing of wire harness for PASM valve unit				
			Symptom:	6600 Workshop campaign				
		08/05/2017	08/05/2017	784 <input type="text"/>	14470 km	1		
			Location:	Campaign complete: WH081 Re-program instrument cluster				
			Symptom:	6600 Workshop campaign				
		16/02/2017	16/02/2017	784 <input type="text"/>	5143 km	1		
			Location:	26770 Reducing agent tank				
			Symptom:	5000 Leaks				
		11/01/2017	12/01/2017	784 <input type="text"/>	15 km	1		
			Location:	99001 Vehicle, front left				
			Symptom:	3011 Dent, bulge				



RAPORT ISTORIC SERVICE AUTO COMPLET | 100% DETALIIAT | DIRECT DIN REPREZENTANTA

